



Little Apple Cars



Automobile Status Report

Prepared For

INVENTORY: R572938A



2015 Kia SOUL

Date May 06, 2024

VIN KNDJP3A52F7147979

Mileage 114518

RO# 6074569

Service Advisor

James Cook

jrocktundra@gmail.com



Little Apple Cars
2828 Amherst Ave
Manhattan, KS 66502

Little Apple Cars Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively with your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.

Multi-Point Inspection Form

RO# 6074569


INVENTORY: R572938A

VIN KNDJP3A52F7147979


Advisor James Cook














































Technician Noah Simmons

















































Created On 5/6/2024

 Checked and OK at this time

 May Require Future Attention

 Requires immediate attention

ROAD TEST			
			BRAKE OPERATION <u>PASS</u>
			ENGINE OPERATION <u>PASS</u>
			DRIVETRAIN OPERATION <u>PASS</u>
			TRANSMISSION OPERATION <u>PASS</u>
LIGHTS			
			TAIL LAMPS <u>PASS</u>
			HEAD LAMPS <u>PASS</u>
			STOP LAMPS <u>PASS</u>
			TURN SIGNALS <u>PASS</u>
			SIDE MARKER LAMPS <u>PASS</u>
			LICENSE PLATE LAMPS <u>PASS</u>
			EMERGENCY FLASHERS <u>PASS</u>
UNDER HOOD			
			BLOCK TEST <u>PASS</u>
			OIL CHANGE <u>PASS</u>
			STEERING LINKS <u>PASS</u>
			FLUID AT LEVELS <u>PASS</u>

FUNCTIONAL			
			HORN <u>PASS</u>
			TIRES <u>PASS</u>
			LF <u>10</u>
			RF <u>10</u>
			LR <u>8</u>
			RR <u>8</u>
			SEAT BELTS <u>PASS</u>
			WINDSHIELD <u>PASS</u>
			PARKING BRAKE <u>PASS</u>
			WIPERS AND WASHERS <u>PASS</u>
			HEATER AND DEFROSTER <u>PASS</u>
			BRAKE PAD MEASUREMENTS <u>PASS</u>
			LF <u>8</u>
			RF <u>8</u>
			LR <u>1</u>
			RR <u>1</u>

Additional Service Recommendations

In the process of inspecting your vehicle for safety and reliability, your technician **Noah S** made the following observations and recommends that you do the necessary repairs to resolve these issues.

Red: requires immediate attention.

Yellow: in need of attention soon.

[Other]: Cabin air filter access cover - locking tabs broken off.

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



Bulb - Back-up Light: Right

Item Description

A back-up light bulb is the bulb to indicate the vehicle has been put into reverse and will begin backing up.

Reason

If not replaced, you will fail the vehicle inspection and could receive a ticket for improper equipment.



Back-up Light

Brake Rotor Replacement - Front: Severe brake pulsation - rotors not resurface-able. Pads measure 8mm - inspect condition.

Item Description

Brake rotors are the parts within the wheels of an automobile which brake pads squeeze in order to slow the rotation of the wheel and bring the vehicle to a stop.

Reason



Brake Rotor

When the pads are replaced, the rotor must be resurfaced smooth to allow the new pads to have an even contact surface to work with. Only a small amount of material can be machined off of a rotor before it becomes unusable and must be replaced. A minimum thickness measurement is stamped on every rotor and the technician doing the brake job will measure the rotor before and after machining it to make sure it doesn't go below the legal minimum. If a rotor is cut below the minimum, it will not be able to handle the high heat that brakes normally generate. This will cause the brakes to "fade," greatly reducing their effectiveness to a point where you may not be able to stop. At this point the brake rotor needs to be replaced.

**Brake Rotor Replacement - Rear:
Severe brake pulsation - rotors not
resurface-able. Pads measure 7mm -
inspect condition.**

Item Description

Brake rotors are the parts within the wheels of an automobile which brake pads squeeze in order to slow the rotation of the wheel and bring the vehicle to a stop.

Reason

When the pads are replaced, the rotor must be resurfaced smooth to allow the new pads to have an even contact surface to work with. Only a small amount of material can be machined off of a rotor before it becomes unusable and must be replaced. A minimum thickness measurement is stamped on every rotor and the technician doing the brake job will measure the rotor before and after machining it to make sure it doesn't go below the legal minimum. If a rotor is cut below the minimum, it will not be able to handle the high heat that brakes normally generate. This will cause the brakes to "fade," greatly reducing their effectiveness to a point where you may not be able to stop. At this point the brake rotor needs to be replaced.



Rotor

***Tire Balance and Rotate: Front 8/32,
Rear 10/32**

Item Description

Balancing the vehicles tires are necessary to make sure the proper weight of the vehicle is distributed to the proper tire. Tire rotation helps protect tires against uneven wear by moving the tire location on the vehicle. Most tires will exhibit some form of wear based on numerous factors including: wheel alignment, miles driven, driving style and habits, and tire location on the vehicle. By moving or "rotating" the tires as recommended by the vehicle manufacturer, tires may wear more evenly; helping extend the life of the tires.



Reason

If not properly balanced, a vehicle's tires can experience abnormal wear which can significantly decrease the life of the tire. If not done, you will experience vibration in the steering wheel at certain highway speeds. Also, vibration will occur in the seat or floorboard at certain highway speeds. Tire wear will become scalloped or cupped.

[Other]: rear pads need replaced due to grooving

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



[Other]: FRONT PADS ARE GLAZED. NEED REPLACED

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



COMPLETED REPAIRS

RO# 6074569 - 5/6/2024 10:23 AM

SERVICE ADVISOR
James Cook
jrocktundra@gmail.com
(785) 539-7441

PREPARED FOR
INVENTORY: R572938A

PRINTED - 5/6/2024
QUOTE EXPIRES - 6/5/2024
REPAIR FACILITY ID -

2015 KIA SOUL
KNDJP3A52F7147979
Mileage 114,518

SERVICE NAME					COST
[Other]: Cabin air filter access cover - locking tabs broken off. (I)					
LABOR	0.00 hours at \$0.00 per hour				\$0.00
PARTS	Qty	Description	Number	Price	Total
	1	access cover	KIAOFMANHATTAN	\$32.69	\$32.69
Parts and labor sub total					\$32.69
Bulb - Back-up Light: Right (I)					
LABOR	0.30 hours at \$165.00 per hour				\$49.50
PARTS	Qty	Description	Number	Price	Total
	1	BULB cq	CQ-921	\$2.99	\$2.99
Parts and labor sub total					\$52.49
Brake Rotor Replacement - Front: Severe brake pulsation - rotors not resurface-able. Pads measure 8mm - inspect condition. (I)					
LABOR	1.00 hours at \$165.00 per hour				\$165.00
PARTS	Qty	Description	Number	Price	Total
	2	rotors OR	921474RGS	\$93.62	\$187.24
Parts and labor sub total					\$352.24
Brake Rotor Replacement - Rear: Severe brake pulsation - rotors not resurface-able. Pads measure 7mm - inspect condition. (I)					
LABOR	1.00 hours at \$165.00 per hour				\$165.00
PARTS	Qty	Description	Number	Price	Total
	2	rotors OR	980957RGS	\$91.88	\$183.76
Parts and labor sub total					\$348.76
*Tire Balance and Rotate: Front 8/32, Rear 10/32 (I)					
LABOR					\$49.95
PARTS					\$0.00
Parts and labor sub total					\$49.95
[Other]: rear pads need replaced due to grooving (I)					
LABOR	0.50 hours at \$165.00 per hour				\$82.50
PARTS	Qty	Description	Number	Price	Total
	1	rear pads (OR)	SC1594	\$84.73	\$84.73
Parts and labor sub total					\$167.23
[Other]: FRONT PADS ARE GLAZED. NEED REPLACED (I)					
LABOR	0.50 hours at \$165.00 per hour				\$82.50
PARTS	Qty	Description	Number	Price	Total
	1	front pads (OR)	SC2094	\$88.12	\$88.12
Parts and labor sub total					\$170.62

Total Labor	\$594.45
Total Parts	\$579.53
Subtotal	\$1,173.98
Shop Charges	\$34.00
Taxes	\$3.11
Total	\$1,211.09



Little Apple Cars
2828 Amherst Ave
Manhattan , KS 66502

(785) 539-7441